



Service Bulletin

File in Section: -


Bulletin No.: 16-NA-305

Date: September, 2016

INFORMATION

Subject: Brake Rotor Cover Removal at Pre-Delivery Inspection (PDI)

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Cascade	2017	2017	September 12, 2016	EOP	All	All

Involved Region or Country	North America
Condition	 <p style="text-align: right; font-size: small;">4583624</p>
Cause	Brake Rotor covers are being implemented in production that need to be removed during the PDI process. Covers have been implemented to reduce corrosion on calipers and rotors during ocean transport stages.

Correction



4583625

If you encounter a vehicle with the above concern, remove the covers.



4583626

Covers are perforated and can be removed by reaching through the wheel, ripping the cover at the perforation and pulling it through the wheel.

Version	1
Modified	

