



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-315

Date: September, 2016

TECHNICAL

Subject: Driver Door Lock Spins when Trying to Lock or Unlock Door

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Spark	2016	2016				

Involved Region or Country	North America
Condition	Some customers may comment that the driver door lock spins when trying to lock or unlock the door.

Correction

If you encounter a vehicle with the above concerns, the key and key cylinder needs to be replaced.

Service Procedure

Refer to *Front Side Door Lock Cylinder Replacement* in SI.

Parts Information

Note: Use the Vehicle Identification Number (VIN), SI, and the GM Electronic Parts Catalog to determine the proper part number to order.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2060220	Front Side Door Lock Cylinder Replacement	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION