



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-320

Date: September, 2016

TECHNICAL

Subject: Exterior Approach Lighting Inoperative

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT6	2016	2016				

Involved Region or Country	North America and N.A. Export Regions
Condition	Some customers may comment that the approach lighting is inoperative.
Cause	This condition may be caused by incorrect performance calibration programmed in the Keyless Entry Control Module (KECM).

Correction

If you encounter a vehicle with the above concern, reprogram the keyless entry control module with the latest calibrations.

Service Information

Refer to *Keyless Entry Control Module Programming and Setup* in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810545	Keyless Entry Control Module Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION