



Service Bulletin

File in Section: -


Bulletin No.: 16-NA-333


Date: October, 2016

TECHNICAL

Subject: Cracked Tail Lamps

Brand:	Model:	Model Year:		Date Breakpoints:		Engine:	Transmission:
		from	to	from	to		
Buick	Regal	2016	2016	April 1, 2016	June 30, 2016	All	All

Involved Region or Country	North America
Condition	 <p style="text-align: right;">4587559</p> <p>Some customers may comment on seeing a crack on the outer lens of the right and/or left tail lamp. In some cases, customers may mention a water leak related to the same area.</p>

<p>Cause</p>	
<p>4587563</p> <p>The cause of the condition may be due to a change in the tail lamp fastening process at the plant. The crack often travels through the fastener (1), as shown in the graphic above.</p>	

Correction

Note: Lamps that are cracked, or damaged due to impact, are normally not considered to be a warranty item, but tail lamps exhibiting this condition should be replaced under warranty.

Replace the affected tail lamp(s). Refer to *Tail Lamp Replacement* in SI.

Parts Information

Note: Use the vehicle identification number (VIN), SI, and the GM Electronic Parts Catalog to determine the proper tail lamp(s) to order.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2041490	Tail Lamp Replacement	Use Published Labor Operation Time

Version	1
Modified	

