



Service Bulletin

INFORMATION

Subject: Engineering Information – Rattle Noise from Second Row Seat

Models: 2015 Cadillac Escalade Models Built Between January 2015 to June 2015
2016 Cadillac Escalade Models Built Between October 2015 to May 2016
2015 Chevrolet Suburban, Tahoe Models Built Between January 2015 to June 2015
2016 Chevrolet Suburban, Tahoe Models Built Between October 2015 to May 2016
2015 GMC Yukon Models Built Between January 2015 to June 2015
2016 GMC Yukon Models Built Between October 2015 to May 2016

This PI has been revised to end the need for information from the field. Please discard PIE0370.

If you encounter a vehicle with this concern, please refer to the latest version of PIT5284.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION