



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** SES Lamp With DTC P015A

**Models:** 2013-2017 Chevrolet Equinox  
2013-2017 GMC Terrain  
Equipped with engine 2.4L LEA

*This PI was superseded to update Models and Model Years. Please discard PIP5389B.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A customer may comment on an SES light with DTC P015A set.

### Recommendation/Instructions

If SI diagnostics have been completed and a repair has not been established, inspect the engine oil level for being overfilled.

If the engine oil level is found to be overfilled, readjust to correct level and re-evaluate the concern.

If the above steps do not lead to a resolution, advise the customer that engineering is aware of this concern and is working on a repair.

To assist engineering, inquire if the customer is utilizing the transmission manual / tap shift feature and record this information on the repair order.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION