

Bulletin No.: PIP5430

Date: Oct-2016

Service Bulletin

PRELIMINARY INFORMATION

Subject: TAC Part Restriction - E41 ECM Part Number 12670950

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado	2017	2017	All	All	6.6 L5P	All
GMC	Sierra	2017	2017	All	All	6.6 L5P	All

Involved Region or Country	North America
Additional RPO/s:	L5P
Condition	As part of our ongoing quality improvement efforts the 2017 Chevrolet Silverados and GMC Sierras equipped with the 6.6L Diesel engine (RPO L5P) E41 ECM Engine Control Module Part number 12670950 will be placed on a parts restriction through the Technical Assistance Center (TAC).
Cause	This parts restriction will assist Engineering with product feedback.

If you require an engine control module (ECM) for a 2017 Chevrolet Silverado or GMC Sierra equipped with the 6.6L Diesel engine (RPO L5P), please complete the following diagnostic questionnaire before you contact TAC.

Is the Restricted part being requested for customer pay? Yes/No

List all DTCs: Are the current (active) DTCs repeatable?

If any turbocharger or fuel related DTCs are set; check for leaks in the air and/or fuel systems. Leaks in the air or fuel system may cause DTCs to set.

What is the battery voltage reading?

Have you completed the appropriate SI documents for the DTCs listed?

What SI documents were used for diagnosis?

What step in the SI document led to replace the ECM?

Parts Information

Description	Part Number	Qty
ECM	12670950	1

Warranty Information

Labor Operation	Description	Labor Time
4025390	Engine Control Module Replacement	1.0 Hr.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

