



Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Tip: -Take Steering- DIC Message Along With Warning Chime/Alert

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade Models	2017	2017	All	All	All	All
Chevrolet	Suburban, Silverado, Tahoe	2017	2017	All	All	All	All
GMC	Sierra, Yukon Models	2017	2017	All	All	All	All

Involved Region or Country	North America
Additional RPO/s:	With Lane Keep Assist RPO UHX
Condition	Some customers may comment of a "Take Steering" message on the DIC along with a warning chime/alert.
Cause	This message does not mean there is a fault with the vehicle. The purpose of the message is to alert the driver that the Lane Keep Assist system has NOT detected active steering input from the driver (hands off the steering wheel).

Correction

Note: At NO point should the driver operate the vehicle with their hands removed from the steering wheel, as serious injury or death could occur. Focus your attention on driving.

Moving the steering wheel will dismiss the alert.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools,

safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION