



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** SES Lamp DTC P1070 setting

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	ATS, CTS	2016	2017	All	All	All	All

<b>Involved Region or Country</b>	North America, Europe, Middle East
<b>Additional RPO/s:</b>	KL9 (ENGINE CONTROL, STOP-START SYSTEM)
<b>Condition</b>	A customer may comment of the MIL lamp on and Auto Stop is inoperative, upon performing diagnostics a P1070 will be found.
<b>Cause</b>	Engineering is investigating.

### Correction

Clear the DTC. Engineering is aware of the issue and is currently researching the concern. If the DTC resets other than when the engine is cranking, continue to follow SI diagnostics.

### Warranty Information

Labor Operation	Description	Labor Time
4081328	Retrieve and Clear ECM Code P1070	.2
	*This is a unique Labor Operation for Bulletin use only.	

<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that

your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION