

# **Service Bulletin**

# PRELIMINARY INFORMATION

## Subject: HPCM2 Fault Code P0606 Control Module Internal Performance

Models: 2011 - 2015 Chevrolet Volt

2014 - 2016 Cadillac ELR

2012 - 2014 Opel Ampera

#### This PI was superseded to update to model years. Please discard PIC5978.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

# **Condition/Concern**

This DTC can set in the Hybrid Powertrain Control Module 2 (K114B) during normal vehicle servicingprocedures such as clearing codes or connecting the 12 volt battery.

## **Recommendation/Instructions**

Review stored data in GDS2 for the vehicle and locate the first time codes were read on this servicevisit. If the first code read includes P0606 from the HPCM2, follow normal service procedures. If the P0606 was not set in the hands of the customer, follow these steps to clear the P0606 in the HPCM2:

- 1. Close all doors and rear hatch
- 2. Press and hold the power button to put the vehicle into service mode.
- 3. Clear the DTC using GDS2
- 4. Power off the vehicle, and
- 5. Open and close the driver's door
- 6. Wait 1 minute
- 7. Start vehicle and ensure MIL is not illuminated

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION