## **GPOP - Issue Review System**

Part Number: 68018109A\$, 68232369A\$

Part Description: Actuator- A/C Heater

**Issue** No heat while in floor or any other mode. Blend door is not moving to heat. **Description:** Before replacing the actuator call Matt Sasina at cell (248) 464-4982.

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.