

1/13/16 MY14, 15 KL

GPOP - Issue Review System

Part Number: 68194950A\$

Part Description: Dual Pane Sunroof and Sunshade Motor

Issue Description: Both the sunroof and sunshade motors must be at version REV 3.0.7. Motors replaced require the same REV level to calibrate successfully. If necessary, replace both motors to match for proper calibration.

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.