



**NUMBER:** 07-001-16

**GROUP:** Cooling

**DATE:** January 09, 2016

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**SUBJECT:**

Belt Tensioner Noise During Cold Start

**OVERVIEW:**

This bulletin involves replacing the belt tensioner.

**MODELS:**

2014 - 2015	(KL)	Jeep Cherokee
2015	(UF)	Chrysler 200

**NOTE:** This bulletin applies to KL vehicles built on or before July 17, 2015 (MDH 0717XX) equipped with 3.2L V6 24V VVT Engine (sales code EHB).

**NOTE:** This bulletin applies to UF vehicles built on or before August 03, 2015 (MDH 0803XX) equipped with 3.6L V6 24V VVT Engine (sales code ERB).

**SYMPTOM/CONDITION:**

The customer may describe a loud high frequency noise that happens within 20 seconds of engine startup and lasts about 90 seconds intermittently during a cold engine start, approximately 0°C (32°F) and below.

**DIAGNOSIS:**

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

**PARTS REQUIRED:**

Qty.	Part No.	Description
1	04627533AC	Tensioner, Belt

**REPAIR PROCEDURE:**

Replace the belt tensioner. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 07 - Cooling> Accessory Drive> Tensioner, Belt> Removal/Installation.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

<b>Labor Operation No:</b>	<b>Description</b>	<b>Skill Category</b>	<b>Amount</b>
07-20-18-92	Tensioner, Belt - Replace (1 - Semi-Skilled)	1 - Engine Repair	0.5 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------