

NUMBER: 09-002-16

GROUP: Engine

DATE: January 16, 2016

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

SUBJECT:

Engine Mounts Replacement

OVERVIEW:

This bulletin involves replacing the right and left engine mounts.

MODELS:

2014 - 2016 (DJ)

Ram 2500 Pickup

NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA.

NOTE: This bulletin applies to vehicles built on or before October 11, 2015 (MDH 1011XX) equipped with 6.4L Engine (sales code ESA).

SYMPTOM/CONDITION:

The customer may describe a drone/noise or excessive vibration condition when the engine is operating in ECO mode.

DIAGNOSIS:

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68090655AA	Insulator, Engine Mount Right Side
1	68090658AA	Insulator, Engine Mount Left Side

REPAIR PROCEDURE:

Replace the left and right side engine mount insulators. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 09 - Engine, 6.4L/Engine Mounting/Insulator, Engine Mount, Engine Mount, Left/Right> Removal/Installation.

POLICY:

Reimbursable within the provisions of the warranty.

09-002-16 -2-

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
09-40-10-98	Engine Mount/support Both Left and Right - Replace (1 - Semi- Skilled)	4 - Chassis Systems	1.4 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------