

A PDF of this newsletter and previous ones can be found by logging in to ServiceNet and clicking on the [Elsa Newsletter](#) section in the Technician References menu.



Audi Elsa Newsletter

Edition 131: April 13, 2015

Content

- [Technical Bulletins](#)
- [Pending Service Solutions](#)
- [Campaigns](#)
- [Updates](#)
- [Suggestions](#)



Technical Bulletins

01 "Oil Level Sensor Oil Change Necessary" message appears - Instructions for reading oil level in 2.0 TDI vehicles (2040260/1)

Model(s)	Year	Vehicle Specific Equipment
A3	2015	TDI clean diesel
Condition:		
• The message "Oil level sens.: oil change necessary. Please contact Service" briefly appears in the information panel when the vehicle is started. • The yellow oil level sensor remains illuminated in the information panel after the message disappears. • The MIL is not illuminated and no DTCs related to the oil level		

sensor are stored.

Production Solution: Not applicable. Vehicle is operating as designed.

97 Rear wiper motor inoperative (2040221/1)

Model(s)	Year	Vehicle Specific Equipment
Q5	2010-2015	Not Applicable
Condition: The rear wiper is not functioning or only functions intermittently. Production Solution: Not applicable.		

Pending Service Solutions

No new Pending Service Solutions this week.

Campaigns

23N4 - Clean Diesel Engine ECM Software Update

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
A3	2010-2014	2.0L TDI®	All	See Campaign/Action screen in Elsa	See Campaign/Action screen in Elsa

The vehicle's engine management software has been improved to assure the vehicle's tailpipe emissions are optimized and operating efficiently.

Under certain operating conditions, the earlier strategy may have increased the chance of the vehicle's MIL light illuminating. If the MIL illuminates for any reason, the vehicle will not pass an IM emissions inspection in some regions.

Updates

No new updates this week.

[Back to top](#)

Suggestions

Please send comments or suggestions to: aoa.workshopinformation@audi.com

[Back to top](#)

© 2015 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.