

Date	Expiration	Release	Page
04.2016	04.2018	1	1(2)

LATCH AND STRIKER PROXIMITY SWITCH – COMPRESSOR DOOR X3-45

Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin install an updated proximity switch on the vehicle compressor door following *Instruction Sheet* [IS-12026](#).

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS	
<i>Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.</i>	
Model	VIN
X3-45 coaches Model Year : 2011 - 2014	From 2PCG33497 BC735005 up to 2PCG33493 EC735572 incl.
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

MATERIAL NEEDED

Order parts according to Instruction Sheet # [IS-12026](#)

PARTS / WASTE DISPOSAL

Return replaced parts to Prevost with A.F.A. for full reimbursement.
Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

Date	Expiration	Release	Page
04.2016	04.2018	1	2(2)

ESTIMATED TIME

The time required to perform this special bulletin is approximately 1.0 hour.

OTHER

VBC Bulletin	N/A
Fail Code	18.04
Defect Code	09
System Condition	B
Causal Part	287286

Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.