

Date	Expiration	Release	Page
05.2016	05.2018	0	1(3)

Initial release .

CLEAN IDLE DECAL ADDITION

Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, an additional decal should be affixed to the engine compartment. Perform the addition to comply with Title 13, California Code of Regulations, Section 1956.8.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS	
Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.	
Model	VIN
H3-45 coaches Model Year : 2016	The following individual vehicles 2PCH33497GC713128, 2PCH33491GC713173 2PCH33496GC713251
X3-45 VIP motorhomes Model Year : 2016	The following individual vehicle 2PCG33492GC735968
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

MATERIAL NEEDED

Order the following parts:

Part No.	Description	Qty
040011	DECAL, M4 MOT CLEAN IDLE EXEMPTION	1

Other parts that may be required:

Part No.	Description	Qty
-	Isopropyl alcohol (Rubbing alcohol)	A/R

Date	Expiration	Release	Page
05.2016	05.2018	0	2(3)

NOTE

Material can be obtained through regular channels.

PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

Clean vehicle structure in the indicated zone with alcohol and apply the enclosed decal #040011.
(Fig. 1 & 2)




Figure 1 X Series Structure, Rear View




Figure 2 H-Series Structure, Rear View

PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

ESTIMATED TIME

The time required to perform this special bulletin is approximately 15 minutes.

OTHER

VBC Bulletin	N/A
Fail Code	04.04-1
Defect Code	09
System Condition	B
Causal Part	040011

Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.