




PREVOST

WARRANTY BULLETIN

WB16-29

DATE :	JUNE 2016	SECTION :	01 - Engine
EXPIRATION:	JUNE 2018		
SUBJECT :	EMS, ACM UPDATE OBD13-GHG14		

Release 1
June 09, 2016

APPLICATION

NOTICE TO SERVICE CENTERS Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.	
Model	VIN
H3-45 coaches Model Year : 2013-2015	The following individual vehicles: 2PCH33499DC712364, 2PCH33497EC712476, 2PCH3349XEC712648, 2PCH33493EC712749, 2PCH33491EC712751, 2PCH33495EC712753, 2PCH33499EC712755, 2PCH33494EC712758, 2PCH33499EC712786, 2PCH33496EC712793, 2PCH33495EC712798, 2PCH33499EC712805, 2PCH33492EC712807, 2PCH33497EC712818
H3-45 VIP motorhomes Model Year : 2013-2015	The following individual vehicles: 2PCVS3499DC712452, 2PCVS3490EC712468, 2PCVS3496EC712524 2PCVS3496EC712555, 2PCVS3498EC712587, 2PCVS3499EC712680 2PCVS3495EC712689, 2PCV33497EC712691, 2PCVS3490EC712715 2PCVS3499EC712728, 2PCVS3493EC712742, 2PCVS349XEC712768 2PCVS3497EC712792, 2PCVS3492EC712800, 2PCVS3498EC712820
X3-45 coaches Model Year : 2013-2015	The following individual vehicles: 2PCG33492EC735465, 2PCG33496EC735470, 2PCG33498EC735471 2PCG33493EC735474, 2PCG33493EC735488, 2PCG33495EC735508 2PCG33491EC735604, 2PCG33493EC735605, 2PCG3349XEC735617 2PCG33493EC735619, 2PCG33491EC735621, 2PCG3349XEC735696 2PCG33491EC735747, 2PCG33490EC735755, 2PCG3349XEC735781 2PCG3349XEC735795, 2PCG33491EC735796
X3-45 VIP commercial use Model Year : 2014-2015	The following individual vehicles: 2PCCS3497EC735642, 2PCC33495EC735766, 2PCCS3496EC735777 2PCCS3490EC735788, 2PCCS3496EC735794.
X3-45 VIP motorhomes Model Year : 2014 - 2015	The following individual vehicles: 2PCBS3491EC735504, 2PCBS3495EC735537, 2PCBS3490EC735740 2PCBS3495EC735779
Volvo 9700, MY 2014	Single vehicle: 3CET2V225E5166754
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

DESCRIPTION

On the vehicles affected by this bulletin, update EMS and ACM software to the latest version available. This update must be carried out by qualified technicians. As soon as possible, make an appointment with your nearest Prevost Service Center or contact your service manager to carry out the update.

MATERIAL

No material is required for this bulletin.

PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop engine.

1. Connect Premium Tech Tool (PTT) to the vehicle diagnostics connector (OBD). Connect the PC to a functional LAN or WiFi connection and a power source.
2. Turn the vehicle ignition switch to "ON".
3. Using PTT, update EMS and ACM software to the latest version available

PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevost's normal warranty. We will reimburse you thirty minutes(s) (30min) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at www.prevostcar.com (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB16-29".

OTHER

VBC Bulletin	TBC
Fail Code	01.00-2
Defect Code	49
Syst. Cond	B
Causal Part	3092091

Access all our Service Bulletins on
<http://techpub.prevostcar.com/en/>
or scan the QR-Code with your smart phone.
E-mail us at **technicalpublications_prev@volvo.com** and type
"ADD" in the subject to receive our warranty bulletins by e-mail.

