

Tech Tips

TT 20-16-04 Date: November 25, 2016

2015-2016 Golf, GTI and Golf Sportwagen – Fuel Gauge Does Not Read Accurately after Performing the 20Y6 Update

January 13, 2017: Update to Information.

If the fuel gauge is found to be reading inaccurate after performing the 20Y6 recall, please perform a minimum 5 minute capacitance discharge on the battery. Recheck fuel gauge for accuracy after the capacitance discharge has been performed.