



# Technical Bulletin

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta (A6)	2011 – 2014	All	All	All	All
Jetta (A6)	2015	All	All	AJ_FM200001	AJ_FM219981
Jetta (A6)	2015	All	All	AJ_FM350001	AJ_FM354021
Golf/GTI (A7)	2015	All	All	AU_FM000001	AU_FM032085
Beetle	2012 – 2014	All	All	All	All
Beetle	2015	All	All	AT_FM600001	AT_FM619716
Beetle Convertible	2013 - 2014	All	All	All	All
Beetle Convertible	2015	All	All	AT_FM800001	AT_FM804950
Passat NMS	2012 – 2014	All	All	All	All
Passat NMS	2015	All	All	A3_FC000001	A3_FC025559

## Condition

57 16 02 February 2, 2016 2038202 Supersedes Technical Bulletin V571404 dated November 5, 2014 to include Door Lock Front Replaced labor operation.

### Front Door Locks Hard to Release

Customer may comment that the front door is hard to open with exterior handle.

## Technical Background

The front door lock operation is affected by various climate or temperature conditions and as a result may require increased effort to release.

## Production Solution

Improved front door locks.



# Technical Bulletin

---

## Service

For concerns of front door lock hard to release from the outside door handle, or the outside handle binds, verify the customer's concern. If the concern can be duplicated, replace the affected door lock to correct the concern. See repair manual group 57 Front Doors, Central Locking System in ELSA. **DO NOT** attempt to correct this concern by performing the following repairs:

- Adjusting or replacing the door striker (The striker should **ONLY** be replaced if there are physical defects)
- Adjusting the mounting position of the door lock to the door.
- Lubricating the door latch, striker, bow or the Bowden cable(s).

 **Note:**

**When verifying the customer's concern described in this bulletin, please note that the condition may not be present if the vehicle is not exposed to the same climate/temperature conditions at which the customer experienced the concern.**

**Before replacing the door lock, perform visual inspection of the door handle to verify normal operation. When the door panel is removed to replace the door lock, verify normal operation of the bow and Bowden cables. These components can also contribute to or cause the concerns described in this bulletin.**



# Technical Bulletin

## Warranty

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual <sup>1)</sup>					
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Jetta (A6)	2011 - 2014	All	All	All	All
Jetta (A6)	2015	All	All	AJ_FM200001	AJ_FM219981
Jetta (A6)	2015	All	All	AJ_FM350001	AJ_FM354021
Golf/GTI (A7)	2015	All	All	AU_FM000001	AU_FM032085
Beetle	2012 - 2014	All	All	All	All
Beetle	2015	All	All	AT_FM600001	AT_FM619716
Beetle Convertible	2013 – 2014	All	All	All	All
Beetle Convertible	2015	All	All	AT_FM800001	AT_FM804950
<b>SAGA Coding</b>					
<b>Claim Type:</b>		Use applicable Claim Type <sup>1)</sup>			
<b>Service Number:</b>	<b>Damage Code</b>	<b>HST</b>		<b>Damage Location (Depends on Service No.)</b>	
5717	0017	--		Use applicable when indicated in Elsa (L/R)	
<b>Parts Manufacturer:</b>		Jetta A6, Golf/GTI A7, Beetle, Beetle Convertible		3ME <sup>2)</sup>	
<b>Jetta A6</b>					
<b>Labor Operation <sup>3)</sup> : Door Lock Front Replaced</b>			57175550 = 10 TU		



# Technical Bulletin

Labor Operation <sup>3)</sup> : Remove and Install Front Door Lock	57171950 = 30 TU	
Labor Operation <sup>3)</sup> : Remove and Install Bowden Cables	57191950 = 10 TU	
Labor Operation <sup>3)</sup> : Remove and Install Front Door Trim Panel	70591900 = 40 TU	
<b>Golf/GTI A7, Beetle, Beetle Convertible</b>		
Labor Operation <sup>3)</sup> : Door Lock Front Replaced	57175550 = 10 TU	
Labor Operation <sup>3)</sup> : Remove and Install Front Door Lock	57171950 = 20 TU	
Labor Operation <sup>3)</sup> : Remove and Install Bowden Cables	57191950 = 10 TU	
Labor Operation <sup>3)</sup> : Remove and Install Front Door Trim Panel	70591900 = 40 TU	
Causal Part:	5K1 837 ***	
<b>Diagnostic Time <sup>4)</sup></b>		
GFF Time expenditure	01500000 = 00 TU max.	NO
Road Test	01210002 = 00 TU 01210004 = 00 TU	NO
Technical Diagnosis	01320000 = 20 TU max.	YES
<b>Claim Comment: Input "As per Technical Bulletin 2038202" in comment section of Warranty Claim.</b>		
<p><sup>1)</sup> Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only</p> <p><sup>2)</sup> Code per warranty vendor code policy.</p> <p><sup>3)</sup> Labor Time Units (TUs) are subject to change with ELSA updates.</p> <p><sup>4)</sup> Documentation required per Warranty Policy Procedures Manual.</p>		



# Technical Bulletin

<b>To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual <sup>1)</sup></b>					
Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
Passat	2012 – 2014	All	All	All	All
Passat	2015	All	All	AT_FM800001	AT_FM804950
<b>SAGA Coding</b>					
<b>Claim Type:</b>	Use applicable Claim Type <sup>1)</sup>				
<b>Service Number:</b>	<b>Damage Code</b>	<b>HST</b>		<b>Damage Location (Depends on Service No.)</b>	
5717	0017	--		Use applicable when indicated in Elsa (L/R)	
<b>Parts Manufacturer:</b>	Passat			WVO <sup>2)</sup>	
<b>Labor Operation <sup>3)</sup>:</b> Door Lock Front Replaced	57175550 = 10 TU				
<b>Labor Operation <sup>3)</sup>:</b> Remove and Install Front door Latch	57171950 = 30 TU				
<b>Labor Operation <sup>3)</sup>:</b> Remove and Install Bowden Cables	57191999 = 10 TU				
<b>Labor Operation <sup>3)</sup>:</b> Remove and Install Front door trim panel	70591900 = 40 TU				
<b>Causal Part:</b>	5K1 837 ***				
<b>Diagnostic Time <sup>4)</sup></b>					
<b>GFF Time expenditure</b>	01500000 = 00 TU max.			NO	
<b>Road Test</b>	01210002 = 00 TU 01210004 = 00 TU			NO	
<b>Technical Diagnosis</b>	01320000 = 20 TU max.			YES	
<b>Claim Comment: Input “As per Technical Bulletin 2038202” in comment section of Warranty Claim.</b>					



# Technical Bulletin

---

- 1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only
- 2) Code per warranty vendor code policy.
- 3) Labor Time Units (TUs) are subject to change with ELSA updates.
- 4) Documentation required per Warranty Policy Procedures Manual.

## Required Parts and Tools

See ETKA for proper vehicle door lock application.

Tool Description	Tool No:
Bone Tool	3409
Torque Wrench	VAG 1331

## Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.