

GPOP - Issue Review System

Part Number: 68249986A\$, 68249987A\$, 68258676A\$, 68258671A\$, 68258673A\$, 68258675A\$, 68261196A\$, 68261195A\$, 68301356A\$, 68301357A\$, 68302271A\$, 68301353A\$, 68302272A\$, 68301354A\$, 68258382A\$, 68258381A\$, 68258383A\$, 68258380A\$, 68258379A\$, 68258384A\$, 68258397A\$, 68258401A\$, 68258398A\$, 68258400A\$, 68258404A\$, 68258403A\$, 68232033A\$, 68258392A\$, 68258396A\$, 68261015A\$, 68258395A\$

Part Description: MY16 RA3 & RA4 Replacement Radios

Issue Description: All MY16 RA3 and RA4 replacement radios must be ordered through the exchange process at United Radio. DO NOT order a NEW radio from Mopar. Go back and order a "Z" level part number. (example: Z8249986A\$)
The MY16 replacement radios must be reconfigured by United Radio to the wireless network provider in order for Uconnect Apps to work properly.

~ Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
