

July 20, 2016 MY 16 D2, DD, DF, DJ, DP

GPOP - Issue Review System

Part Number: 05086755A\$, 05086754A\$, 05015705A\$

Part Description: Rear Crank Shaft Oil Seal and retainer plate

Issue For Cummins equipped vehicles only;~

Description: If replacing Rear Main Seal for oil leak, replace seal and retainer as a set PN; 9003466. Please do not disturb seal in retainer when removing from engine.~ Cummins Engineering is currently investigating the root cause of the oil leak concern. If there are any questions, please contact Chad Eichbrecht at cell (248) 309-2695~ If you do not receive a response within 15 minutes, please proceed with normal repair. ~ Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.