

9003491 10/30/2016 MY15, 16, 17 VM

## GPOP - Issue Review System

**Part Number:** 68100532A\$, 68103577A\$, 68261916A\$, 68261720A\$, 68280720A\$, 68261862A\$, 68247204A\$, 68103420A\$, 68103421A\$, 68103422A\$, 06106272A\$, 06106273A\$, 06106085A\$, 68100682A\$, 68032108A\$, 52129436A\$, 68241596A\$, 68261722A\$, 68261723A\$, 68261861A\$, 68241593A\$

**Part Description:** RESISTOR- Blower Motor, Blower Motor, Any AC Line, Compressor, Condenser

**Issue Description:** For VM bodies ONLY; Prior to replacing this part, Please contact Karl Sonnenberg at Cell (248) 563-7740 prior to replacing the component. If you do not receive a response within 15 minutes, please continue with normal repair procedure. RETURN ALL PARTS. Put End Caps on all Lines. Describe where leak in line was detected. Take photo and email to [karl.sonnenberg@external.fca.com](mailto:karl.sonnenberg@external.fca.com).

~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.  
~