

9003642 11/16/2017 MY17 RU

## **GPOP - Issue Review System**

**Part Number:** 5RL34DX9A\$, 5RL34PD2A\$

**Part Description:** Glove Box Assembly

**Issue Description:** Prior to replacing glove box assembly for glove box light stays on, verify the glove box door is latched completely on both sides. The glove box door should not be able to be pulled open without using glove box handle.~

Please call Mack Allen at (248) 944-0140 prior to replacing the glove box assembly. If you don't receive a response within 15 minutes, please continue with normal repair procedure.~

~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.  
~