

NUMBER: 08-090-16

GROUP: Electrical

DATE: November 22, 2016

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 16-103. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Shortened Battery Life

OVERVIEW:

This bulletin involves replacing the battery.

MODELS:

2017 (LD) Dodge Charger 2017 (LX) Chrysler 300

NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA.

NOTE: This bulletin applies to vehicles built on or after October 14, 2016 (MDH 1014X) and on or before October 25, 2016 (MDH 1025XX).

SYMPTOM/CONDITION:

Possible short battery life.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

PARTS REQUIRED:

Qty.	Part No.	Description
1	BB0H7730AA	Battery

08-090-16 -2-

REPAIR PROCEDURE:

NOTE: No testing is required for this RRT, just replace the battery.

 Replace the battery. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info>08 - Electrical/8F - Engine Systems/Battery System/Battery/Removal/Installation.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

NOTE: The Labor Operation No (LOP) is unique to this RRT and no GR8 printout will be needed for warranty. The LOP can NOT be used on other vehicle outside of the RRT VIN list. If this LOP is used on other vehicles, the dealer will be charged back.

Labor Operation No:	Description	Skill Category	Amount
08-08-01-95	Battery - Replace (1 - Semi-Skilled)	6 - Electrical And Body Systems	0.4 Hrs.

FAILURE CODE:

ZZ Service Action
