

1/26/16

MY15, 16

RT

GPOP - Issue Review System

Part Number: 05109399A\$

Part Description: Deflector Shield

Issue Description: Engineering is investigating a rattle noise from the underbody of the vehicle possibly caused by a loose spare tire heat shield. If the fastener is loose or missing, please note on the RO.~
Before securing the heat shield to the vehicle, please contact Louie Miranda at cell (519) 984-1852.~
If you do not receive a response within 15 minutes, proceed with securing the heat shield to the vehicle.~

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedure unrelated to this Tech Tip or part order inquiries. Please include the concerned part number and Tech Tip part description of of the Tech Tip you are referencing for our tracking system.
