GPOP - Issue Review System

Part Number: 05150945A\$, 05150879A\$, 68243303A\$, 68243305A\$

Part Description: Powertrain Control Module

Issue If a PCM/ECM is being replaced due to liquid being present inside of the PCM/ECM Description: electrical connector(s) on a 2015-2016 model year 5.7L Hemi DS, D2, DD, DJ or DX truck, please call Lou Nigro at cell (810) 293-3858. If no response is received within 15 minutes, please continue with repair.~

> Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.