


PREVOST

WARRANTY BULLETIN

WB16-33

DATE :	OCTOBER 2016	SECTION :	01 - Engine
EXPIRATION:	OCTOBER 2018		
SUBJECT :	ENGINE INFORMATION DECAL REPLACEMENT		

APPLICATION

NOTICE TO SERVICE CENTERS	
<i>Verify vehicle eligibility by looking up warranty bulletin status in SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.</i>	
Model	VIN 
H3-41, H3-45 coaches Model Year : 2015 - 2017	From 2PCH33496 <u>FC712695</u> up to 2PCH33498 <u>HC713480</u> incl.
H3-45 VIP motorhomes Model Year : 2015 - 2017	From 2PCVS3497 <u>FC712694</u> up to 2PCVS3496 <u>HC713435</u> incl.
<p>This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.</p>	

DESCRIPTION

On the vehicles affected by this bulletin, replace the engine information decal located in the engine compartment.

Specifically, the decal located on the engine valve cover is correct, but the copy of the decal located on the vertical panel has wrong engine family information. You have to remove the copy and replace it with the replacement decal.

CORRECTIVE MEASURES

To ensure conformity with EPA regulations, the decal must be replaced by a *certified Prevost technician*. Contact your nearest Prevost Service Center to schedule an appointment and have this modification performed at your earliest convenience. Have in hand your Vehicle Identification Number (VIN) and the warranty bulletin number WB16-33.

Since decals are vehicle specific, allow a few days for the order to reach your local Service Center.

A list of all Prevost Service Centers is available on <https://www.prevostcar.com/service-network>

Technicians, please refer to SCI16-40 complete instructions.

PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

WARRANTY

This modification is covered by Prevost's normal warranty and will be performed free of charge. The estimated time required to execute this bulletin is fifteen minutes.

OTHER

VBC Bulletin	N/A
Fail Code	18.08
Defect Code	09
Syst. Cond	B
Causal Part	012824

Access all our Service Bulletins on
<http://techpub.prevostcar.com/en/>
or scan the QR-Code with your smart phone.
E-mail us at **technicalpublications_prev@volvo.com** and type
"ADD" in the subject to receive our warranty bulletins by e-mail.

