

NOTE: This Technical Service Bulletin will be valid within (1) year from the original date of publication.

ACTION REQUIRED:

Inspect Magnum Inverter/s to confirm Model and serial number
Replace ONLY Inverter/s Model MS2812 with serial number H1-34600 through H1-34830

MODELS / UNITS:

2016 Aspire	G13B	8097-8109
	G13H	8068-8069
	G13N	8081-8085
	G13P	8055-8056
	G13U	8071-8072
2016 Anthem	G14A	8052-8053
	G14B	8145-8171
	G14H	8067-8071
	G14L	8062
	G14N	8092-8103
2016 Cornerstone	G16A	8067-8071
	G16B	8106-8121
	G16K	8071-8072

PARTS KIT

Please Contact Sensata's Technical Support if a replacement
Magnum inverter/s is required
1-425-353-8833

Inverter/s Model number and Serial number/s **MUST** be noted on claim submitted to Jayco prior to processing for payment.





Fig 1: Aspire inverter is located inside 2nd compartment forward of the rear wheels, passenger side.

Fig 2: A **single** inverter is located inside the compartment between the frame rails.



Fig 3: Anthem / Cornerstone inverters are located in 3rd compartment forward of rear wheels on either side .

Fig 4: Anthem & Cornerstone have **dual** inverters located between the frame rails.



903 South Main Street | P.O. Box 460 | Middlebury, IN 46540 | 800-945-4787 | www.entegracoach.com

March 2016

Technical Service Bulletin Notification TSB #16-007

Dear Valued Entegra Dealer:

Entegra Coach has determined that certain Model Year 2016 Aspire, Anthem and Cornerstone Class A motor homes require inspection of the Magnum inverter/s for possible replacement.

Magnum Dimensions released Service Bulletin 160209 regarding the circuitry inside certain Magnum inverter/chargers that may fail over time due to an incorrect FET circuit board installed.

Our records indicate the following affected Entegra motor homes are currently stock units at your Dealership. Affected units that are currently stock should be repaired prior to being retail sold.

Serial number

The coverage period for this Technical Service Bulletin is for one (1) year from the release of this notification. (March 2016-March 2017) If you have sold the vehicle/s listed, please contact the current owner regarding this Service Bulletin and process the Warranty Registration of your customer. All information concerning this TSB is available to you on Entegra's Dealer website under the Service and Parts Tab. If you have questions, please contact Entegra Customer Service at 800-517-9137.

We certainly regret this inconvenience; however the satisfaction of our Customers is important to us.

Sincerely

Entegra Coach

SERVICE BULLETIN Number: 160209

The purpose of this bulletin is to inform Jayco about the need to inspect, and if necessary, replace the Magnum inverter/s.

Date Released: February 2016

Reference: Magnum inverter/charger model **MS2812** within a serial number range starting with **H1-34600** and ending with **H1-34830** may be impacted.

Condition: Circuitry inside certain Magnum inverter/chargers may fail due to an incorrect FET Printed Circuit Board (i.e., FET Board) that may have been installed.

Inspection: Remove and inspect the Magnum inverter/s to determine each inverter's serial number.

1. Open the motor home's electrical compartment containing the Magnum inverter/s.
2. View the model and serial number label on the side of the inverter/s.




Figure 1, MS2812 Model/Serial Number Label

2. If the serial number **is not** within the serial number range, the internal FET board is correct and no further inspection is required.
3. If the serial number **is** within the serial number range, replace the MS2812 inverter/charger.
4. If you have an inverter that needs to be replaced, contact Sensata's Technical Support team for Magnum products at 1-425-353-8833 (8AM to 5PM PST Monday – Friday) for assistance in obtaining a replacement inverter.

Labor Allowance: Sensata allows **30 minutes** for product inspection, and **1 hour** of labor for product removal / re-installation.

If you have any questions concerning this bulletin, contact Magnum Technical Support at:
1-425-353-8833



ENTEGRA
COACH®

903 South Main Street | P.O. Box 460 | Middlebury, IN 46540 | 800-945-4787 \ www.entegracoach.com

March 2016

Technical Service Bulletin Notification TSB #16-007
Unit :

Dear Valued Entegra Coach Owner:

Entegra Coach has determined that certain Model Year 2016 Aspire, Anthem and Cornerstone Class A motor homes require inspection of the Magnum inverter/s for possible replacement.

Magnum Dimensions released Service Bulletin 160209 regarding the circuitry inside certain Magnum inverter/chargers that may fail due to an incorrect FET circuit board installed.

Our records indicate that your Class A motor home is affected by this Service Bulletin. Please contact an Entegra Dealer to schedule an appointment and present this letter as authorization to have the procedure completed at no cost to you.

The coverage period for this Technical Service Bulletin is for one (1) year from the release of this notification. (March 2016 – March 2017) If you have sold or traded your vehicle or for any reason cannot have this service performed, please contact the Entegra Customer Service Department at 800-517-9137.

We certainly regret this inconvenience; however your satisfaction with your Entegra motor home is important to us.

Sincerely

Entegra Coach