

**On-car analysis list from February 8th, 2016**  
**please contact VW Helpline before attempting repair**

	<b>Models</b>	<b>MY</b>	<b>Engine</b>	<b>Transmission</b>	<b>Topic</b>	<b>Customer Complaint</b>
<b>Powertrain</b>	Jetta Hybrid	13 - 15	All	All	P309F and P309D Fault Code	Mil-on no electric drive mode, untouched vehicles
	Touareg	11-15	3.0L (CATA/CNRB)	All	P0087/Fuel Pump Noise/Crank-No-Start	Customer states crank no start, in-tank fuel pump making noise, possibly with P0087 (No previous repairs for High Pressure Pump concerns)
	Passat	12 and 14	2.0TDI (CKRA)	All	P0202A and/or P202B in ECM	MIL-on with <u>static</u> fault code P202A and or P202B (MY12 and 14 only, no MY13)
	Tiguan	15	All	All	Rear O2 Sensor Fault	MIL-on fault P013E in the ECM
	Jetta, Passat, Jetta Sportwagen, Beetle, Beetle Conv	14	2.0TDI (CKRA, CJAA)	All	EGR Fault	MIL-on fault code P046C (untouched vehicles only)
	Jetta, Passat, Beetle, Beetle Conv	14-15	1.8T (CPRA, CPKA) 2.0T (CPPA, CPLA)	All	Upper Timing Cover	Engine Oil leak, upper timing cover leaking oil
	Passat, Jetta, Golf Sportwagen, Beetle, Beetle Conv	15	2.0TDI (CVCA, CURA)	All	MIL on P164B	Customer states MIL on, P164B in ECM (untouched vehicles, Engine production before January 2015 or after March 2015 <b>only</b> )
	Jetta	16	1.4T (CZTA)	All	P0456 Fault Code	MIL-on with P0456 <b>(untouched vehicles California ONLY)</b>
<b>Chassis</b>	Golf /GTI (A7)	16	All	All	Strut Noise (2/3/2016)	Customer states there is a noise while turning/ going over bumps (noise from strut bearing/mount area)
	All	16	All	All	Alignment	Vehicle alignment not correct, steering off center, pulls, drifts, during PDI (no prior alignment repairs)
<b>Body</b>	Jetta, Passat	15-16	All	All	Door Lock	Any MFI "Door Ajar" concern (Vehicle VIN ranges: <b>Jetta</b> FM219981 – FM350000 or after FM354021 / <b>Passat</b> after FC025559)
	Golf Sportwagen	15-16	All	All	Sunroof Water Drain	Water leak from sunroof/headliner, water stains on headliner