



# Technical Bulletin

---

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All Except Routan	2010-2017	All	All	All	All

## Condition

40 16 02 October 25, 2016 2040561 Supersedes by V401501 dated May 6, 2015 to add additional model year applicability.

### Squeaking Noises from Front of Vehicle

Squeaking/creaking noise from front of vehicle while fully turning steering wheel.

## Technical Background

The ribs of the outer CV boot may contact one another when the steering wheel is fully turned. This has the possibility to create a squeak or creak noise. The noise may be more prevalent in wet weather.

## Production Solution

No production change required.

## Service

If the noise is determined to be coming from the outer CV boot ribs coming in contact with each other, no further work is required. Please explain to the customer that this is a normal condition and may be more noticeable in wet weather.



### Note:

This contact does not affect the service life or the function of the components and is considered normal. **DO NOT** replace parts for this concern.



# Technical Bulletin

---

## Warranty

Information only.

## Required Parts and Tools

No Special Parts required.

No Special Tools required.

## Additional Information

**All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.**

Document Control Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2040561/2	10/25/16	V401602	Update model year applicability.
2040561/1	5/6/15	V401501	Original publication.