



Technical Journal

TITLE:

Difficult to add/program remote key, T8

REF NO: TJ 31698.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2016-06-29	STATUS DATE: 2016-07-07
FUNC GROUP: 3400	FUNC DESC: Ignition system (Not for new design 2004)	Page 1 of 4	

“Right first time in Time”

Attachment

File Name	File Size
TJ31698 .jpg	0.1865 MB
TJ31698_2.JPG	0.5190 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256	BC	B1BPHEV					2016-9999		0000000-9999999	201526-999952

CSC Customer Symptom Codes

Code	Description
3D	Accessory installation/Accessory installation
XI	Remote control/Does not work

VST Operation Number

DTC Diagnostic Trouble Codes



Text

DESCRIPTION:

If you experience difficulty programming remote keys on T8 vehicles, please follow the advice under **SERVICE**.

SERVICE:

Carry out VIDA fault tracing of any related DTCs.

If the problem is still present:

- 1) Place the remote in the position shown in attachment. The Volvo logo must face outward. Proceed to add key.
- 2) If it is still difficult to add keys, unfasten the center console and lift the rear of the console several inches/centimeters from the car body as shown in attachment. Proceed to add key.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 3661.

To view TJ attachment continue to next page. This TJ has two attachments.



