

8/17/16

MY16 VF

GPOP - Issue Review System

Part Number: 68242417A\$, 68242422A\$, 68268174A\$, 68268175A\$, 68268176A\$, 68233854A\$, 68233855A\$

Part Description: Body Control Module (BCM)

Issue Description: If looking to replace a VF Promaster BCM because there is a Diagnostic Trouble Code of: | B1007-18 | Active | Turn Light Left - Circuit current below threshold BCM | B1008-18 | Active | Turn Light Right - Circuit current below threshold. Please check to make sure the turn signals in the outside mirror(s) are functional prior to ordering and replacing the BCM.

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.