

1 05 32-16**Service Information Bulletin**

| SUBJECT | DATE |
|------------------|----------|
| SPN 524286 (TCM) | May 2016 |

Additions, Revisions, or Updates

| Publication Number / Title | Platform | Section Title | Change |
|----------------------------|--------------|------------------|---------------------|
| DDC-SVC-MAN-0140 | DT12 | SPN 524286/FMI 2 | This is a new code. |
| DDC-SVC-MAN-0084 | Transmission | | |

DiagnosticLink users: Please update the troubleshooting guides in DiagnosticLink with this newest version. To update the tool troubleshooting guide, open DiagnosticLink and from the Help – Troubleshooting Guides menu, select the appropriate troubleshooting manual, then click Update.



13400 Outer Drive, West, Detroit, Michigan 48239-4001
 Telephone: 313-592-5000
www.demanddetroit.com

2 SPN 524286/FMI 2

This fault indicates CPC is incorrectly programmed, no shift map present. Reprogram the CPC with the latest server configuration.