# ΤΟΥΟΤΑ

# PRODUCT SUPPORT DIVISION

INTEROFFICE MEMORANDUM

Published: 6/13/2016

| From: Bob Waltz<br>Group Vice-President, Product Quality and Service Suppo | port |
|--|------|

| Subject: | Special Service Campaign (SSC) G0G – <i>Remedy Notice</i> |
|----------|---|
|          | Certain 2015-2016 Model Year Sienna Vehicles              |
|          | Oxygen Sensor Replacement                                 |

## Specific information for Region support is provided below.

### **Condition**

The subject vehicles are equipped with an Oxygen Sensor which could experience wire degradation inside the Oxygen Sensor wiring harness caused by vehicle vibration during normal operation. If this occurs, the vehicle will illuminate the check engine light.

#### **Dealer Notification**

The attached dealer letter will be sent to all Toyota dealers in Mid-June, 2016.

Please reference the attached Dealer Letter for additional details.

Please review this notification with your staff to assure that all relevant personnel have been briefed regarding this subject.

Thank you for your cooperation.