

### **Tech Tip** T-TT-0390-16

April 03, 2016

Rear Differential leak, noise, loose fasteners.

USA

Drivetrain
Applicability

Axle/Differential

2016 Tacoma

# **APPLICABLE VEHICLES**

2016 Tacoma

### **CONDITION**

Some vehicles may exhibit a fluid leak from the rear differential carrier to axle housing gasket. The differential may exhibit noise or the fasteners may be loose. See the example below for reference:



### RECOMMENDATIONS

- 1. Please create a TAS case and contact Technical Assistance [TAS] to submit details on any vehicle identified matching the condition described in this document prior to repair.
- 2. If you are attempting to contact TAS on a weekend or TMS holiday, continue with diagnosis and submit the requested information on the next available work day. Retain all replaced parts and technician notes for possible review with TMS, TAS, and Product Engineer.

## **LINK REFERENCES**

This Tech Tip does not contain any link references