

Subject		Market
<b>Transfer Case Input Shaft Leak</b>		USA
Service Category	Section	
Drivetrain	Transfer/4wd/Awd	
Applicability		
2014-2016MY GX460		

**APPLICABLE VEHICLES**

2014-2016

GX460

**CONDITION**

Certain vehicles may exhibit a leak from the input shaft seal on the transfer case assembly. This leak is typically first identified by gear oil colored fluid collecting at the bottom of the seam between the transmission output and transfer case input mating surfaces. See example photos below:

Mating surface seam**RECOMMENDATIONS**

- Please do not disassemble. Take a picture of the condition and serial number of transmission, then create a TAS case and contact Technical Assistance (TAS) to submit details on any vehicle identified matching the condition described in this document prior to repair.
- If you are attempting to contact TAS on a weekend or TMS holiday, continue with diagnosis and submit the requested information on the next available work day. Retain all replaced parts and technician notes for possible review with TMS TAS Product Engineer.

**LINK REFERENCES**

This Tech Tip does not contain any link references