



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-140

Date: May, 2016

TECHNICAL

Subject: Erratic Functionality of the ICS Touch Display When Performing A Swiping Motion Across the Display

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu (VIN Z)	2016	2017			All	All
Chevrolet	Volt	2016	2017			All	All

Involved Region or Country	NORTH AMERICA
Condition	Some customers may comment on erratic functionality of the ICS touch display when performing a swiping motion across the display.
Cause	This may be caused by an internal software calibration.
Additional Options	Equipped with radio RPOs IO5 or IO6

Correction

If you encounter a vehicle with the above concern, reprogram the radio control with the latest software. Refer to *Radio Control Programming and Setup* in SI.

Warranty Information

Labor Operation	Description	Labor Time
2810325	Radio Control Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION