



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-154

Date: May, 2016

TECHNICAL

Subject: Diagnostic Tip for Malfunction Indicator Lamp (MIL) Illuminated, DTC U18A2 and/or P018B

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu (VIN Z)	2016	2016				

Involved Region or Country	North America and Israel
Condition	Some customers may comment that the MIL is illuminated. Technician may find DTC U18A2 and/or P018B set.

Correction

Perform diagnostic test procedure for the codes. Refer to the Diagnostic Trouble Code procedures in SI.

If normal diagnostic testing has found no faults, inspect the connector and terminals at the Fuel Pump Control Module for proper pin fit. Refer to *Testing for Intermittent Conditions and Poor Connections* in SI.

Warranty Information

For vehicles repaired under warranty, use the appropriate labor operation for the repair performed.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION