



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-357

Date: October, 2016

TECHNICAL

Subject: Integrated Center Stack and/or Instrument Panel Cluster Backlighting Seems Dim at Times

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Envision	2016	2017			All	All

Involved Region or Country	North America and China
Condition	Some customers may comment at times the IPC (instrument panel cluster) and/or ICS (integrated center stack – radio display) is not bright enough.
Cause	This may be due to the current software/calibration that doesn't allow the IPC to transition quickly between night/day ambient lighting and may not seem bright enough.

Correction

If you encounter a vehicle with the above concern, reprogram the BCM with the latest calibrations. Refer to *Body Control Module Programming and Setup* in SI.

Important: Once reprogramming is complete, verify that backlighting is brighter by adjusting the interior dimming switch.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION