

Model series 190 cracking between loading floor and side trunk lining

Topic number	LI68.30-P-063994
Version	1
Design group	68.30 Coverings, trim
Date	05-02-2016
Validity	AMG GT (190)
Reason for change	
Reason for block	

Complaint:

Gap between loading floor and side trunk lining

Cause:

Gaps that were identified in loading floor.

Remedy:

1. Remove lining at side of trunk, see ar68.30-p-4800rg.
2. Print out template (see Attachment) in DIN A3 format.
3. Position template, see picture 1.
4. Position block of foam, see picture 2, Position A and B. press firmly on.

Attachments	
File	Description
Schablone_C190_Schaumklotz_kleben.pdf	Template
Positionierung Schablone.JPG	Figure 1
Positionierung Schaumklötze 1.JPG	Figure 2

Symptoms
Body / Interior equipment / Interior trim / Bad fitting

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
68-0000	NON PUNCH FOR THIS		69A33 38	
			69N33 38	


Attachments

XENTRY TIPS

Positionierung Schablone.JPG:



Positionierung Schaumklötze 1.JPG:



XENTRY TIPS

