

XENTRY TIPS

Model series 190 roller sun blind opens by itself during high acceleration

Topic number	LI77.21-P-064066
Version	1
Design group	77.21 Panoramic roof
Date	05-10-2016
Validity	Model series 190
Reason for change	
Reason for block	

Complaint:

Roller sun blind moves back on its own at high acceleration.

Cause:

Holding ability in closed position insufficient.

Remedy:

Replace roller sun blind.

Symptoms

Body / Roof system / Tilting/sliding sunroof system / Inaccurate fit

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 190 810 00 00			Roller sun blind	1		X

Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
77-6983	REPLACE ROLLER SUNBLIND		78021 K8	