

XENTRY TIPS

Model series 190 flap on armrest sticks

Topic number	LI68.20-P-064071
Version	1
Design group	68.20 Center console
Date	05-10-2016
Validity	Model series 190
Reason for change	
Reason for block	

Complaint:

Flap on armrest sticks.

Cause:

Insufficient spring force on stowage compartment lid.

Remedy:

Replace stowage compartment A1906803800.

Symptoms

Body / Interior equipment / Interior trim / Bad fitting

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 190 680 38 00			Stowage compartment	1		X

Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
			68119 D6	