

## Outside door handle does not return to end position

Topic number	LI80.20-P-064069
Version	1
Design group	80.20 Central locking system
Date	05-10-2016
Validity	C/A 453 up to VIN end number K122319
Reason for change	
Reason for block	

### Complaint:

When operated, the outside door handle on the front doors may not automatically return to the fully closed position.

### Cause:

In isolated circumstances, weather influences can lead to sluggishness in the door handle.

### Remedy:

Replace outside door handle.

<b>Symptoms</b>
Body / Door/Flap / Door / Door handle / Jammed

<b>Parts</b>						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 453 720 01 75			LEFT OUTSIDE DOOR HANDLE			X
A 453 720 02 75			RIGHT OUTSIDE DOOR HANDLE			X

<b>Operation numbers/damage codes</b>				
Op. no.	Operation text	Time	Damage code	Note
			72B01 D6	