

2014 and newer G63 slow acceleration from rolling stop

Topic number	LI27.60-P-064011
Version	1
Design group	27.60 Gearshift, control
Date	05-23-2016
Validity	G63 with transmission 722.9 MY14 and newer
Reason for change	
Reason for block	

Complaint:

After braking to a near stop and then performing a heavy tip-in, a small pause is felt before vehicle accelerates

Cause:

Transmission is requesting engine torque reduction to allow for comfortable shift

Remedy:

Vehicle is functioning as designed.

Please create a PTSS Info case with EEPROM referencing this LI for complaint tracking