

---

## Instrument cluster: No display in instrument cluster

---

Topic number	LI54.30-P-063675
Version	1
Design group	54.30 Instrument cluster/display instruments/warning devices
Date	03-22-2016
Validity	117, 156, 166, 242, 246, 292, 463 With Code 806
Reason for change	
Reason for block	

---

### Complaint:

The contents of the instrument cluster display disappear while driving.

Attachments	
File	Description
Beanstandung.JPG	Complaint

### Cause:

Under analysis.

### Remedy:

The fault can be temporarily rectified by changing menus in the instrument cluster or by an ignition cycle.

### Note:

PTSS cases are not needed.

Replacing parts, updating the software or SCN coding does not remedy the problem. This LI will be updated with a fix as soon as possible.

Symptoms
Communication/information / Information display / Displays / Multifunction display / Function / Nonfunctional
Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Menu items missing
Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Incomplete display
Communication/information / Information display / Displays / Multifunction display / Multifunction display, menu / Faulty display

Attachments
-------------

---

# XENTRY TIPS

Beanstandung.JPG:

