

Door seal on B-pillar detaches / protrudes

Topic number	LI68.30-P-063993
Version	1
Design group	68.30 Coverings, trim
Date	04-29-2016
Validity	MODEL 190.3## up to VIN 004769
Reason for change	
Reason for block	

Complaint:

Door seal on B-pillar detaches / protrudes

Cause:

Bonded connection

Remedy:

Replace component with problem (see Position A picture attachment), the faulty component is not to be reused or stuck on again.

Note: Thoroughly clean bonding surface using cleaner A0059891971.

Attachments	
File	Description
Bild B-Säule.JPG	Picture of B-pillar

Symptoms
Body / Door/Flap / Door / Trim / Loose
Body / Door/Flap / Door / Trim / Fits poorly

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 005 989 19 71			Cleaner	1		X
A 190 691 01 00			Cover on B-pillar, left	1		X
A 190 691 02 00			Cover on B-pillar, right	1		X

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			67A08 38	

XENTRY TIPS

			67N08 38	
--	--	--	----------	--

Attachments

Bild B-Säule.JPG:

