

Running board illumination inoperative

Topic number	LI82.10-P-064405
Version	1
Design group	82.10 Exterior lights
Date	06-30-2016
Validity	MODEL 166.0 with illuminated running board (accessory)
Reason for change	
Reason for block	

Complaint:

One or more LEDs inoperative or reduced light output with A 166 906 18 01 illumination kit for running boards.

Cause:

Failure of one or more LED modules.

Remedy:

Installation of repair kit A 166 906 34 03. Contains wiring harness and five LED modules for one side of the vehicle.

Note: In case of repairs, install all five modules from the repair kit in order to avoid differences in light output.

Note: Installation as per WIS instructions AZ82.10-P-0015GQ.

Symptoms
Overall vehicle / Lighting / Exterior lights / Standing/parking lights / Standing lights / Nonfunctional
Overall vehicle / Lighting / Exterior lights / Standing/parking lights / Parking lights / Nonfunctional
Overall vehicle / Lighting / Exterior lights / Signal lights / Rotating beacon / Nonfunctional
Overall vehicle / Lighting / Exterior lights / Driving lights / Ambient illumination / Nonfunctional

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A1669063403			Running board illumination repair kit	1	For one side of vehicle. For further information please refer to the ODUS system.	

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			58806 73	Running board courtesy lights - Electrical fault

XENTRY TIPS

WIS-References			
Document number	Title	Note	Allocation
AZ82.10-P-0015GQ	Retrofit illumination for running boards		Remedy