

Vibration in steering wheel at highway speeds

Topic number	LI46.35-P-064579
Version	1
Design group	46.35 Electric steering
Date	07-27-2016
Validity	Model 253
Reason for change	
Reason for block	

Complaint:

Vibration / noise felt in steering wheel and potentially throughout the body floor area at highway speeds over shallow bumps.

Cause:

Under investigation

Remedy:

There is currently no repair measure available for this complaint. Once a measure is available, this document will be updated with the appropriate remedy.

In order to validate the condition, unplug the connector at ES (N68). Once the connector is removed, the vibration / noise should be eliminated or significantly reduced when traversing shallow bumps at highway speeds.

Note: Please do not replace any parts at this time.

Symptoms
Chassis/suspension / Steering system / Noises / Humming/vibrations
Chassis/suspension / Suspension/Dampening / Suspension system noises / Metallic noise
Chassis/suspension / Suspension/Dampening / AIRMATIC / Noises / Thumping/rumbling
Chassis/suspension / Steering system / Steering wheel / Vibrates

Validity		
Vehicle	Engine	Transmission
GLC (253)	*	*