

Rough 3-2 shift while decelerating

Topic number	LI27.00-P-063826
Version	1
Design group	27.00 General
Date	04-08-2016
Validity	GLE450 Coupe (292) with transmission 725.0
Reason for change	
Reason for block	

Complaint:

3-2 downshift is occasionally rough when braking

Cause:

Under investigation

Remedy:

Please create a PTSS case and attach the following information:

- Initial quicktest
- VGS control unit log
- EEPROM *.txt file before any adaptation
- Current oil level (Please check and verify)

Symptoms
Power transmission / Automatic transmission / Function / Shifting is rough
Power transmission / Automatic transmission / Function / Poor shift quality